

Final Reclamation Inspection

November 16th, 2023

Operator: Conoco Phillips Company - 19160

Location ID: 385889

Inspection Document #: 714000137

La Plata County, CO

Township: SENW 31 34N 10W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Argenta 34-10 31-1
Location ID: 385889



Photo 1. View of the project area taken from the entrance facing center.



Inspection Photos

Location Name :Argenta 34-10 31-1

Location ID: 385889




Photo 2. Cardinal photos taken from the center of the project area.
Left photo facing north, right photo facing east.

Inspection Photos

Location Name :Argenta 34-10 31-1

Location ID: 385889





Photo 3. Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

API #:067-05515

Inspection Photos

Location Name : Argenta 34-10 31-1

Location ID: 385889




Photo 4. View of rill erosion forming along the access road at the entrance point of the well disturbance.

Inspection Photos

Location Name : Argenta 34-10 31-1

Location ID: 385889




Photo 5. View of several bare patches observed along the access road that need additional reclamation.

Inspection Photos
Location Name : Argenta 34-10 31-1
Location ID: 385889



Photo 6. Reference area comprised of gambel oak and smooth brome.