

Final Reclamation Inspection

November 20th, 2023

Operator: Benson Montin and Greer - 10663

Location ID: 333805

Inspection Document #: 714000144

La Plata County, CO

Township: NWSW 5 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: La Posta 5
Location ID: 333805



Photo 1. View of the project area taken from the southern edge facing center.



Inspection Photos
Location Name : La Posta 5
Location ID: 333805



Photo 2. View of western edge of the project area facing southeast.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515

Inspection Photos
Location Name : La Posta 5
Location ID: 333805



Photo 3. View of northern project area. Evidence of tracking and hydro-mulch observed. Area is dominated by an undesirable plant species, kochia and does not appear consistent with adjacent reference area, additional reclamation is needed.

Inspection Photos
Location Name : La Posta 5
Location ID: 333805



Photo 4. View of debris observed in the western project area.



Inspection Photos
Location Name : La Posta 5
Location ID: 333805



Photo 5. Reference area comprised of gambel oak, smooth brome and pine.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515