

Final Reclamation Inspection

November 16th, 2023

Operator: Benson Montin Greer Drilling
Corporation - 7650

Location ID: 325319

Inspection Document #: 714000166

La Plata County, CO

Township: SWNW 4 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Jacques 1
Location ID: 325319



Photo 1. View of the project area taken from the western edge facing east.



Inspection Photos
Location Name :Jacques 1
Location ID: 325319




Photo 2. Cardinal photos taken from the center of the project area.
Left photo facing north, right photo facing east.

Inspection Photos
Location Name :Jacques 1
Location ID: 325319



Photo 3. Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west. Note: project area is dominated by an undesirable plant species Kochia, and does not appear consistent with the adjacent reference area.

Inspection Photos
Location Name : Jacques 1
Location ID: 325319



Photo 4. Reference area comprised of sagebrush, smooth brome and poa secunda.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515