

**Inspection Photos**  
**Location: Red Rocks 35-11**  
**Facility ID: 484360**



**Photo 1 –Well Site Placard at access road**



**Photo 2 – Well location looking north, Impacted soil**

**Inspection Photos**  
**Location: Red Rocks 35-11**  
**Facility ID: 484360**



**Photo 3 – Wellhead and open trench**

**Photo 4 – Unused equipment on location**



**Inspection Photos**  
**Location: Red Rocks 35-11**  
**Facility ID: 484360**



**Photo 5 – Unused equipment**

**Photo 6 – Drill Cuttings pile, Cellar and pipeline trench material**

**Inspection Photos**  
**Location: Red Rocks 35-11**  
**Facility ID: 484360**



**Photo 7 – Drill Cuttings not properly stored**



**Photo 8 – Drill cuttings in native pasture**



**Inspection Photos**  
**Location: Red Rocks 35-11**  
**Facility ID: 484360**



**Photo 9 – Area impacted by white substance**

**Photo 10 – Area impacted by white substance**



**Inspection Photos**  
**Location: Red Rocks 35-11**  
**Facility ID: 484360**



**Photo 11 – White substance**



**Photo 12 – Access road, there are signs of vehicle traffic outside established r-o-w**

