

Inspection Photos
Location: Red Rocks 35-08
Facility ID: 484359



Photo 1 –Well Site Placard at access road

Photo 2 – Access road looking east

Inspection Photos
Location: Red Rocks 35-08
Facility ID: 484359



Photo 3 – Wellhead and placard

Photo 4 – Location looking southeast

Inspection Photos
Location: Red Rocks 35-08
Facility ID: 484359



Photo 5 – Location looking north



Photo 6 – Location Looking west, debris in the form of trees



Inspection Photos
Location: Red Rocks 35-08
Facility ID: 484359



Photo 7 – Drill cuttings



Photo 8 – Drill cuttings berm

Inspection Photos
Location: Red Rocks 35-08
Facility ID: 484359



Photo 9 – unknown material not properly stored

