

Inspection Photos
Location: Red Rocks 1-14
Facility ID: 484357



Photo 1 –Well Site Placard not properly set

Photo 2 – Well location looking south

Inspection Photos
Location: Red Rocks 1-14
Facility ID: 484357



Photo 3 – Drill Cuttings



Photo 4 – Topsoil Pile, Drill Cuttings, and excavated material from Gathering Line Trench

Inspection Photos
Location: Red Rocks 1-14
Facility ID: 484357



Photo 5 – Open Excavation



Photo 6 – Topsoil Pile, Gathering Line Trench Material with no BMPs

Inspection Photos
Location: Red Rocks 1-14
Facility ID: 484357



Photo 7 – Open Trench



Photo 8 – Topsoil Pile with impacts from Drill Cuttings