

Inspection Photos
Location: Red Rocks 1-16
Facility ID: 484358




Photo 1 – Well Site Placard Not Properly set

Photo 2 – Wellhead and open gathering line trench

Inspection Photos
Location: Red Rocks 1-16
Facility ID: 484358



Photo 3 – Topsoil Stock Pile

Photo 4 – Open Gathering line trench

Inspection Photos
Location: Red Rocks 1-16
Facility ID: 484358



Photo 5 – Open Cuttings Trench

Photo 6 – Location Looking South

Inspection Photos
Location: Red Rocks 1-16
Facility ID: 484358



Photo 7 – Drill Cuttings with no Liner or containment

Photo 8 – Drill Cuttings with no Liner or containment

Inspection Photos
Location: Red Rocks 1-16
Facility ID: 484358



Photo 9 – Area of impact from Drill Cuttings

Photo 10 – Area impacted by Drill Cuttings

Inspection Photos
Location: Red Rocks 1-16
Facility ID: 484358



Photo 11 – Drill Cuttings Trench and Drill Cuttings