

Interim and Stormwater Inspection

November 15, 2023

Operator: Kerr McGee Oil & Gas- #47120

Location ID: 434325

Inspection Document #: 709400641

Weld County, CO

NENE Section 21 T2N R66W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: 3D/36N-21HZ
Location ID: 434325



Photo 1. Photo taken of location sign at wellhead, facing west.



Photo 2. Photo taken of tank battery on pad. Photo taken facing northwest.

Inspection Photos
Location Name: 3D/36N-21HZ
Location ID: 434325

Nov 15, 2023 at 10:45:37 AM
Fort Lupton CO 80621
United States



Photo 3. Photo taken of weeds (Mullen) on site. Photo taken facing east.

Nov 15, 2023 at 10:45:45 AM
Fort Lupton CO 80621
United States



Photo 4. Photo taken of weeds (Mullen) on site. Photo taken facing southeast.

Inspection Photos
Location Name: 3D/36N-21HZ
Location ID: 434325

Nov 15, 2023 at 10:46:29 AM
Fort Lupton CO 80621
United States



Photo 5. Photo taken of replanted flowline path from wells to tank battery. Photo taken facing east.

Nov 15, 2023 at 10:47:49 AM
Fort Lupton CO 80621
United States



Photo 6. Photo of close up of replanted flowline path from wells to tank battery. Photo taken facing east.

Inspection Photos
Location Name: 3D/36N-21HZ
Location ID: 434325

Nov 15, 2023 at 10:49:10 AM
Fort Lupton CO 80621
United States



Photo 7. Photo taken of bare area in reclaimed field. Photo taken facing east.

Nov 15, 2023 at 10:50:31 AM
Fort Lupton CO 80621
United States



Photo 8. Photo taken of weeds (longspine sandbur) on site. Photo taken facing north.

Inspection Photos
Location Name: 3D/36N-21HZ
Location ID: 434325

Nov 15, 2023 at 10:51:32 AM
Fort Lupton CO 80621
United States



Photo 9. Photo taken of perennial grasses and weeds (russian thistle & kochia) . Photo taken facing south.

Nov 15, 2023 at 10:51:47 AM
Fort Lupton CO 80621
United States



Photo 10. Photo taken of weeds (russian thistle & kochia)debris on lodged in fencing . Photo taken facing northwest.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400641

Inspection Photos
Location Name: 3D/36N-21HZ
Location ID: 434325

Nov 15, 2023 at 10:52:14 AM
Fort Lupton CO 80621
United States



Nov 15, 2023 at 10:52:21 AM
Fort Lupton CO 80621
United States



Photo 11. Photo taken of concrete on pad. Photo taken facing south.

Photo 12. Photo taken of concrete on pad. Photo taken facing south.

Inspection Photos
Location Name: 3D/36N-21HZ
Location ID: 434325

Nov 15, 2023 at 10:57:31 AM



Nov 15, 2023 at 10:57:39 AM



Photo 13. Photo taken of white salted crusted area on access to tank battery. Photo taken facing northeast.

Photo 14. Photo taken of white salted crusted soil next to access road to tank battery. Photo taken facing east.

Inspection Photos
Location Name: 3D/36N-21HZ
Location ID: 434325

Nov 15, 2023 at 10:58:29 AM



Photo 15. Photo taken of white salted crusted soil in field next to access road to tank battery in. Photo taken facing northwest looking toward the access road from the field..

Nov 15, 2023 at 10:59:21 AM



Photo 16. Photo taken of white salted crusted area on access to tank battery. Photo taken facing northeast.