



00061127

**COLORADO OIL & GAS CONSERVATION COMMISSION**  
**FIELD INSPECTION REPORT**

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- 123 - 8649		LEASE NAME: CHAMPLIN 41-14 #1	
LOCATION: NE NE 14 IN 68W		OPERATOR: UPRC	
DATE: 1/17/96		INSPECTOR: SHELTON	
Insp. Type: PR	Insp. Status: PR	PA: Y N	Pass/Fail: (P) F Viol.: Y (N) NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210)	OK	
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904)	NONE	
<b>Fences</b> (Rule 604.C.(3), 1003.A)		
<b>Tank Battery Equipment</b> (Rule 604)	To SE 900'	
<b>Fire Walls/Berms/Dikes</b> (Rule 604)	OK	
<b>General Housekeeping</b> (Rule 603.G)	OK	
<b>Spills (Oil/Water)</b> (Rule 908)		
<b>Bradenhead</b> (Rule 207)		
<b>Drilling Well/Workover</b> (Rule 315)		
<b>Surface Rehabilitation</b> (Rule 317)		
<b>Miscellaneous</b>	PUMP JACK ACTIVE	

**CORRECTIVE ACTION REQUIRED:**

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site