

Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 120-27 Pad

Location # 324065



Photo # 7794 From entrance to location




Photo # 7795 Location/battery sign missing API #'s

Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 120-27 Pad

Location # 324065

Nov 28, 2023 at 12:13:35 PM



Photo # 7796 Location

Nov 28, 2023 at 12:10:55 PM



Photo # 7797 Location



Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 120-27 Pad

Location # 324065



Photo # 7798 Location



Photo # 7799 Debris