

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NWNE

Location ID: 335274

Date: 11/27/2023



Wellheads – Photo #07685



Separators – Photo #07690

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NWNE

Location ID: 335274

Date: 11/27/2023



Tank Battery – Photo #07691



Equipment Stored on Location – Photo #07687

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NWNE

Location ID: 335274

Date: 11/27/2023



Soil Stockpile Protection has been Removed – Photo #07688



Soil Stockpile Protection has been Removed – Photo #07689