

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location ID: 324177

Date: 11/27/2023



Wellhead – Photo #07680



Separator – Photo #07681

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location ID: 324177

Date: 11/27/2023



Tank Battery – Photo #07683



Sediment Encroaching on Production Equipment – Photo #07682