

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: Chico/4-65 26-25

Loc ID: 455198

Inspection: 709400618



Exhibit A

CA: Failure to control and manage undesirable plant species (Long spine sandbur) to prevent the spread of seeds onto adjacent lands. Mowing is not sufficient management control for this species. See inspection photos 10 & 11. Comply with Rule 606.c. The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date the location was observed out of compliance.

CA Resolution: Operator has reported that the location has been sprayed with herbicide to treat noxious weeds to comply with Rule 606.c.