

Interim Reclamation and Stormwater Inspection

Date: 11/09/2023

Operator: Bonanza Creek Energy Operating
Company LLC. - 8960

Location ID: 432287

Inspection Document #: 713900095

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Location ID: 432287



Photo 1. The photo was taken from the location entrance facing Southeast and illustrates the location sign.

Inspection Photos
Location Name: Antelope B-33 Pad
Location ID: 432287



Photo 2. The photo was taken from the location facing Southeast. The photo illustrates tumbleweeds piling against the Southeast corner fence.




Photo 3. The photo was taken from the location facing Southeast. The photo illustrates an unprotected slope along the East side of the pad.

Inspection Photos

Location Name: Antelope B-33 Pad

Location ID: 432287



Photo 4. The photo was taken from the location facing Southwest. The photo illustrates the tank batteries on location.

Photo 5. The photo was taken from the location facing Northwest. The representative photo of the interim illustrates that all the interim areas have been mowed on the location.

Inspection Photos
Location Name: Antelope B-33 Pad
Location ID: 432287



Photo 6. The photo was taken from the location facing South. The photo illustrates personal tire tracks running throughout the interim areas.

Photo 7. The photo was taken from the location facing Southwest. The photo illustrates a large area of bare soil along the interim reclamation area on the West of the location.

Inspection Photos
Location Name: Antelope B-33 Pad
Location ID: 432287



Photo 8. The photo was taken from the location exit facing Southwest. The photo illustrates debris left on location.



Photo 9. The photo was taken from the location exit facing Southeast. The photo illustrates tumbleweeds being piled just outside the location boundary fence and not being disposed of.

Inspection Photos
Location Name: Antelope B-33 Pad
Location ID: 432287



Photo 10. The photo was taken from the location facing Northeast. The photo illustrates stained soil where oil and gas equipment appeared to be previously.