

**OUT OF SERVICE DESIGNATION**

Rule 434.d. Out of Service Designation and Plugging List. An Operator will designate a Well as Out of Service on a Form 6A, Out of Service Designation, and the Out of Service Well is then placed on the Operator's Plugging List.

OPERATOR & CONTACT INFORMATION

OGCC Operator Number: 10746	Contact Name and Telephone:
Name of Operator: BLACKROCK ENERGY CORP	Name: Andrew Fleming
Address: 242 LINDEN STREET	Phone: (970) 294-6033
City: FORT COLLINS State: CO Zip: 80524	Email: aif@blackrockenergy.us

WELL PLUGGING DATA

The number of Wells the Operator has plugged in the previous 12 months: _____

EVIDENCE OF FINANCIAL CAPABILITY

Provide evidence that the Operator is financially capable of meeting the timelines required by Rule 434.d.(4) for its Plugging List. (If this space is inadequate, provide as an attachment.)

Pursuant to Colorado Oil and Gas Conservation Commission ("Commission") Rule 702.c.(6).D., Blackrock Energy Corp. hereby submits this Certification of Financial Capability as evidence that Blackrock Energy Corp. is financially capable of meeting all of the obligations imposed by the Act and Commission's Rules. My certification is based on my review of Blackrock Energy Corp.'s financial statements and records, including the company's most recent publicly filed annual and quarterly financial statements.

OUT OF SERVICE DESIGNATION

Summary of Wells to be Designated as Out of Service and placed on the Operator's Plugging List

Within 2000' of a School Facility 0	Within 2000' of a Residential Building Unit within a Disproportionately Impacted Community 0
Within 2000' of a Child Care Center 0	
Within 2000' of a High Occupancy Building Unit 0	Within High Priority Habitat 0
TOTAL NUMBER OF WELLS 7	Detected Leak on Operator's CDPHE/AQCC Reg 7 Delayed Repair List 0
Valid 7 Invalid 0	

Form Submit Date: 12/01/2023

Plugging Due Date For Wells: 12/31/2027

#	Inv	API	Well Name & Number	Date Ceased Production or Utilization	Within 2000' of a School Facility?	Within 2000' of a Child Care Center?	Within 2000' of a High Occupancy Building Unit?	Within 2000' of a Residential Building Unit within a Disproportionately Impacted Community?	Within High Priority Habitat?	Detected Leak on Operator's CDPHE/AQCC Reg 7 Delayed Repair List?
1		069-05156	CLARKS LAKE MUDDY SAND UNIT N-1	01/01/1999	No	No	No	No	No	No
2		069-06241	REDWIN 22-71	05/01/2023	No	No	No	No	No	No
3		069-06263	REDWIN 22-75	11/21/2019	No	No	No	No	No	No
4		069-06218	REDWIN 22-1	05/01/2016	No	No	No	No	No	No
5		069-06239	REDWIN 22-6	04/01/2023	No	No	No	No	No	No
6		069-06247	REDWIN 22-64	10/01/2022	No	No	No	No	No	No
7		069-06233	REDWIN 22-5	04/01/2022	No	No	No	No	No	No

OPERATOR COMMENT AND SUBMITTAL

I hereby certify all statements made on this form are, to the best of my knowledge at the time of submittal, true, correct, and complete.

--

Print Name: Jessica DonahueEmail: jdonahue@ardorenvironmental.comTitle: Compliance SpecialistDate: 12/01/2023**Attachment Check List****Att Doc Num****Name**

403608355	EDD-DESIGNATION
403612068	EVIDENCE OF FINANCIAL CAPABILITY

Total Attach: 2 Files