

Inspection Photos

Location Name: HOWARD USX A-66N64W/9SWSW

Location #: 306348




Photo #1

Howard USX A 9-13 (123-24494) Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: Initial plug(s)



Photo #2

Howard USX A 9-13 Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: Initial plug(s)

Site safety signage



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: HOWARD USX A-66N64W/9SWSW
Location #: 306348



Colorado Energy & Carbon Management Commission
Weld County
+40.496211, -104.564410
26° NE
2023-11-30 12:36

Photo #3
Howard USX A 9-13 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Initial plug(s)
Wellsite entrance

tools **stop work authority** **PIC pre-job checklist** **15-minute risk assessment** **safety action review** **tools**

rockies business unit (RBU)
RBU Job #101

job safety analysis (JSA) form
roles, contingency and response

the human energy company

Date and Time: 11-30-23 6:30 AM
Location Name: HOWARD USX A 9-13
Location: 46.44708336 -104.56441049
Master Area: 007HSE
Job Description: PMA

Case of Emergency Call: 910 File See Note
PIC Phone Number: 970-830-7901
CHRON RBU 24-hour OIC Contact: 970-304-5286
RESCUE: N/A
Weather: 59° 46°
Wind: 3 mph
Direction: 175°

Location Sketch: (see: as needed for info)
* Master Area
* Working Area
* Caution/Yellow Area
* Danger/Red Area
* Power Lines
* Pipelines/Locates
* Critical Distance/Clearance

SIMOPS Review:
No SIMOPS activities and no work orders
Ultimate Work Authority (UWA)
Name: Grande Tracy
SHOP Activity: PIC

Identify Procedure Check-It:
1. All procedures are approved and signed by the PIC
2. All procedures are approved and signed by the PIC
3. All procedures are approved and signed by the PIC
4. All procedures are approved and signed by the PIC
5. All procedures are approved and signed by the PIC
6. All procedures are approved and signed by the PIC
7. All procedures are approved and signed by the PIC
8. All procedures are approved and signed by the PIC
9. All procedures are approved and signed by the PIC
10. All procedures are approved and signed by the PIC

Work Crew Sign-off: (see: as needed for info)
Every person that could be impacted by this job must LEGIBLY sign-off including their COMPANY NAME.
At the end of the job, the PIC must sign-off the job and the person who signed the job must be the same person who signed the job at the start of the job.

Personnel:
Guillermo Morales
Erick Morales
Abel Morales
Ornelis Gutierrez
Ricardo Acosta
Joseph Saranense
Benjamin Silveira

Person in Charge: [Signature]

Colorado Energy & Carbon Management Commission
Weld County
+40.496211, -104.564410
26° NE
2023-11-30 12:36

Photo #4
Howard USX A 9-13 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Initial plug(s)
JSA: 2023-11-30



Inspection Photos

Location Name: HOWARD USX A-66N64W/9SWSW

Location #: 306348



Colorado Energy & Carbon Management Commission
Weld County
+40.496208, -104.561274
103° E
2023-11-30 12:36

Photo #5

Howard USX A 9-13 Battery site

Plugged & Abandoned | PA

Plugging Ops; Cementing: Initial plug(s)

Battery sign



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources