

Inspection Photos

Location Name: TREBOR-65N64W/11SENW

Location ID: 326889



Photo #1

Trebor B11-6 (123-13817) Wellsite

Temporarily Abandoned | TA

CA: Overgrown Vegetation



Photo #2

Trebor B11-6, 11-3, 11-18, 11-20, 11-21 Battery site

Inactive | Shut-down

Formerly served:

Trebor B11-4, B 11-19 ;

Plugged & Abandoned | PA

Equipment Documented; Loc ID: 326889



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources