

Inspection Photos

Location Name: TREBOR-65N64W/11NENW

Location ID: 326886



Photo #1

Trebor B11-3 (123-13814) Wellsite
Temporarily Abandoned | TA



Photo #2

Trebor B11-6, 11-3, 11-18, 11-20, 11-21 Battery site
Inactive | Shut-down
Formerly served:
Trebor B11-4, B 11-19 ;
Plugged & Abandoned | PA
Equipment Documented; Loc ID: 326889



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources