

## Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-67S96W/6SWNW

Location ID: 334811

Date: 11/28/2023



Location Entrance – Photo #07715



Wellheads – Photo #07719

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-67S96W/6SWNW

Location ID: 334811

Date: 11/28/2023



Separators – Photo #07718



Tank Battery – Photo #07721






## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-67S96W/6SWNW

Location ID: 334811

Date: 11/28/2023



Tank Battery – Photo #07716



Open-Ended Vent/Load Line – Photo #07717