

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ARCO-66S96W/31SENE

Location ID: 335222

Date: 11/28/2023



Nov 28, 2023 at 10:13:36

Wellheads – Photo #07729



Nov 28, 2023 at 10:15:39  
Parachute CO 81635  
United States

Separators – Photo #07732



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ARCO-66S96W/31SENE

Location ID: 335222

Date: 11/28/2023



**Tank Battery – Photo #07731**



**Insufficient Erosion Controls – Photo #07733**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ARCO-66S96W/31SENE

Location ID: 335222

Date: 11/28/2023



**Insufficient Erosion Controls – Photo #07734**