

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/32SWNW

Location ID: 335372

Date: 11/28/2023



Location Entrance – Photo #07736



Wellheads – Photo #07737

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/32SWNW

Location ID: 335372

Date: 11/28/2023



Separators – Photo #07740



Tank Battery – Photo #07739