

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ARCO-66S96W/29NESE

Location ID: 335184

Date: 11/28/2023



**Location Entrance – Photo #07742**



**Wellheads – Photo #07743**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ARCO-66S96W/29NESE

Location ID: 335184

Date: 11/28/2023



**Separators – Photo #07744**



**Tank Battery – Photo #07745**