

Inspection Photos
Location Name: TREBOR/B11-65-1HN
Location ID: 326701



Photo #1

TREBOR/B11-65-1HN pad Wellsites
2: Producing | PR
1: Temporarily Abandoned | TA



Photo #2

Trebor B11-65-1HN (123-37193) Wellsite
Producing | PR



Inspection Photos
Location Name: TREBOR/B11-65-1HN
Location ID: 326701



Photo #3

Jenkins B11-79-1HCM (123-37194) Wellsite
Producing | PR



Photo #4

Leeroy B11-79HNM (123-37192) Wellsite
Temporarily Abandoned | TA



Inspection Photos

Location Name: TREBOR/B11-65-1HN

Location ID: 326701



Photo #5

**Trebor B11-65-1HN, Jenkins B11-79-1HCM,
Leeroy B11-79HNM Battery site **Active****

Formerly served:

Trebor B11-12 ;

Plugged & Abandoned | PA

Equipment Documented; Fac ID: 326701



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources