

Inspection Photos
Location Name: RRR&S 6-5
Location ID: 320780

Nov 28, 2023 at 12:13:49 PM
39.642372,-104.475268
Wapahoe County
ECMC



Pic 1 wellhead / separator / ECD

Nov 28, 2023 at 12:14:17 PM
39.642113,-104.475434
Wapahoe County
ECMC



Pic 2 Tanks / crypto equipment

Inspection Photos
Location Name: RRR&S 6-5
Location ID: 320780

Nov 28, 2023 at 12:14:42 PM
39.641866,-104.475459
Wapahoe County
ECMC



Pic 3 berm needs to be repaired



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources