

Interim and Stormwater Inspection

November 8, 2023

Operator: Crestone Peak Resources Operating- #10633

Location ID: 437846

Inspection Document #: 709400647

Arapahoe County, CO

SESW Section 13 T5S R65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: State La Plata 5-65 13-15
Location ID: 437846

Nov 8, 2023 at 11:57:26 AM
Watkins CO 80137
United States



Photo 1. Photo taken of location sign at wellhead, facing south.

Nov 8, 2023 at 11:58:56 AM
Watkins CO 80137
United States



Photo 2. Photo taken of wells on site. Photo taken facing southwest.

Inspection Photos
Location Name: State La Plata 5-65 13-15
Location ID: 437846

Nov 8, 2023 at 11:57:51 AM
Watkins CO 80137
United States



Photo 3. Photo taken of tank battery on pad. Photo taken facing southeast.

Nov 8, 2023 at 11:58:10 AM
Watkins CO 80137
United States



Photo 4. Photo taken of interim reclaimed area of perennial grasses. Photo taken facing northeast.

Inspection Photos
Location Name: State La Plata 5-65 13-15
Location ID: 437846

Nov 8, 2023 at 12:00:00 PM
Watkins CO 80137
United States



Photo 5. Photo taken of interim reclaimed area of improperly installed wattle. Photo taken facing northwest.

Nov 8, 2023 at 12:00:20 PM
Watkins CO 80137
United States



Photo 6. Photo of drainage leading to sediment basin, and weeds (russian thistle) indicated by arrow. Photo taken facing west.

Inspection Photos

Location Name: State La Plata 5-65 13-15

Location ID: 437846

Nov 8, 2023 at 12:00:33 PM
Watkins CO 80137
United States



Photo 7. Photo taken of interim reclaimed area of weeds (russian thistle). Photo taken facing west.

Nov 8, 2023 at 12:00:56 PM
Watkins CO 80137
United States



Photo 8. Photo taken of weeds (canada thistle). Photo taken facing north.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400647

Inspection Photos
Location Name: State La Plata 5-65 13-15
Location ID: 437846

Nov 8, 2023 at 12:00:58 PM
Watkins CO 80137
United States



Photo 9. Photo taken of weeds (canada thistle) in rock overflow from sediment basin. Photo taken facing west.

Nov 8, 2023 at 12:04:22 PM
Watkins CO 80137
United States



Photo 10. Photo taken of weeds (russian thistle & kochia) in interim reclaimed area. Photo taken facing southeast.

Inspection Photos

Location Name: State La Plata 5-65 13-15

Location ID: 437846

Nov 8, 2023 at 12:05:43 PM
Watkins CO 80137
United States



Nov 8, 2023 at 12:05:48 PM
Watkins CO 80137
United States



Photo 11. Photo taken of weeds (russian thistle & kochia) in interim reclaimed area. Photo taken facing southeast.

Photo 12. Photo taken of close up of russian thistle and kochia. Photo taken facing east.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400647

Inspection Photos

Location Name: State La Plata 5-65 13-15

Location ID: 437846

Nov 8, 2023 at 12:06:04 PM
Watkins CO 80137
United States



Photo 13. Photo taken of weeds (russian thistle & kochia) in interim reclaimed area. Photo taken facing south.

Nov 8, 2023 at 12:05:54 PM
Watkins CO 80137
United States



Photo 14. Photo taken of weeds (russian thistle & kochia) in interim reclaimed area. Photo taken facing northeast.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400647