

Interim and Stormwater Inspection

November 8, 2023

Operator: Renegade Oil & Gas - #74165

Location ID: 437846

Inspection Document #: 709400649

Arapahoe County, CO

NENE Section 24 T5S R65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: State of CO 5-24HZ
Location ID: 423626

Nov 8, 2023 at 12:12:44 PM
31390 E Quincy Ave
Watkins CO 80137
United States



Photo 1. Photo taken of location sign at wellhead, facing northeast.

Nov 8, 2023 at 12:18:19 PM
31390 E Quincy Ave
Watkins CO 80137
United States




Photo 2. Photo taken of well on site. Photo taken facing northeast.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400649

Inspection Photos
Location Name: State of CO 5-24HZ
Location ID: 423626

Nov 8, 2023 at 12:21:58 PM
31390 E Quincy Ave
Watkins CO 80137
United States



Photo 3. Photo taken of tank battery on pad and separator.
Photo taken facing south.

Nov 8, 2023 at 12:19:02 PM
31390 E Quincy Ave
Watkins CO 80137
United States



Photo 4. Photo taken of interim reclaimed area of perennial
grasses and forbes. Photo taken facing southeast.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400649

Inspection Photos
Location Name: State of CO 5-24HZ
Location ID: 423626

Nov 8, 2023 at 12:19:04 PM
31390 E Quincy Ave
Watkins CO 80137
United States



Photo 5. Photo taken of interim reclaimed area of perennial grasses and forbes. Photo taken facing east.

Nov 8, 2023 at 12:20:14 PM
31390 E Quincy Ave
Watkins CO 80137
United States



Photo 6. Photo of equipment on site. Photo taken facing northeast.

Inspection Photos

Location Name: State of CO 5-24HZ

Location ID: 423626

Nov 8, 2023 at 12:21:14 PM
31390 E Quincy Ave
Watkins CO 80137
United States



Photo 7. Photo taken of interim reclaimed area of perennial grasses and forbes. Photo taken facing west.

Nov 8, 2023 at 12:21:26 PM
31390 E Quincy Ave
Watkins CO 80137
United States



Photo 8. Photo taken of weeds (russian thistle). Photo taken facing north.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400649

Inspection Photos
Location Name: State of CO 5-24HZ
Location ID: 423626

Nov 8, 2023 at 12:21:31 PM
31390 E Quincy Ave
Watkins CO 80137
United States



Photo 9. Photo taken of weeds (kochia) on site. Photo taken facing west.

Nov 8, 2023 at 12:21:33 PM
31390 E Quincy Ave
Watkins CO 80137
United States




Photo 10. Photo taken of weeds (russian thistle & kochia) in interim reclaimed area. Photo taken facing north.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400649

Inspection Photos
Location Name: State of CO 5-24HZ
Location ID: 423626



Photo 11. Photo taken of stained soil under equipment next to well head. Photo taken facing northwest.



Photo 12. Photo taken of weeds (russian thistle & kochia) in interim reclaimed area. Photo taken facing west.

