

Interim and Stormwater Inspection

November 8, 2023

Operator: Crestone Peak Resources Operating- #10633

Location ID: 465461

Inspection Document #: 709400633

Arapahoe County, CO

SENE Section 2 T5S R65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: State Massive 5-65 3-2
Location ID: 4465461

Nov 8, 2023 at 11:20:22 AM
Watkins CO 80137
United States



Photo 1. Photo taken of location sign at wellhead, facing east.

Nov 8, 2023 at 11:23:19 AM
Watkins CO 80137
United States



Photo 2. Photo taken of wells on site. Photo taken facing southeast.

Inspection Photos
Location Name: State Massive 5-65 3-2
Location ID: 4465461

Nov 8, 2023 at 11:22:09 AM
Watkins CO 80137
United States



Photo 3. Photo taken of tank battery on pad. Photo taken facing northeast.

Nov 8, 2023 at 11:24:29 AM
Watkins CO 80137
United States



Photo 4. Photo taken of interim reclaimed area of perennial grasses on the lower portion and weeds (russian thistle) on the upper portion. Photo taken facing west.

Inspection Photos
Location Name: State Massive 5-65 3-2
Location ID: 4465461

Nov 8, 2023 at 11:24:32 AM
Watkins CO 80137
United States



Photo 5. Photo taken of interim reclaimed area of mostly weed (russian thistle). Photo taken facing southeast.

Nov 8, 2023 at 11:24:35 AM
Watkins CO 80137
United States



Photo 6. Photo of close up of russian thistle. Photo taken facing south.

Inspection Photos

Location Name: State Massive 5-65 3-2

Location ID: 4465461

Nov 8, 2023 at 11:24:37 AM
Watkins CO 80137
United States



Photo 7. Photo taken of interim reclaimed area of mostly weed (russian thistle). Photo taken facing east.

Nov 8, 2023 at 11:25:20 AM
Watkins CO 80137
United States



Photo 8. Photo taken of interim reclaimed area of predominantly weeds (russian thistle). Photo taken facing north.

Inspection Photos

Location Name: State Massive 5-65 3-2

Location ID: 4465461

Nov 8, 2023 at 11:26:25 AM
Watkins CO 80137
United States



Photo 9. Photo taken of topsoil stockpile perennial grasses and weeds (russian thistle & kochia) . Photo taken facing north.

Nov 8, 2023 at 11:27:56 AM
Watkins CO 80137
United States



Photo 10. Photo taken of topsoil stockpile of weeds (russian thistle & kochia) . Photo taken facing south.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400633

Inspection Photos

Location Name: State Massive 5-65 3-2

Location ID: 4465461

Nov 8, 2023 at 11:29:13 AM
Watkins CO 80137
United States



Nov 8, 2023 at 11:32:34 AM
Watkins CO 80137
United States



Photo 11. Photo taken of stormwater drainage and erosion of soil. . Photo taken facing east. Blue arrow indicates stormwater erosion.

Photo 12. Photo taken of stormwater erosion alongside rock rundown on east side of pad.. Photo taken facing west.

Inspection Photos

Location Name: State Massive 5-65 3-2

Location ID: 4465461

Nov 8, 2023 at 11:33:21 AM
Watkins CO 80137
United States



Photo 13. Photo taken of topsoil stockpile on east side of pad, majority of vegetation is weeds (russian thistle & kochia). Photo taken facing east.

Nov 8, 2023 at 11:33:24 AM
Watkins CO 80137
United States



Photo 14. Photo taken of topsoil stockpile on east side of pad, majority of vegetation is weeds (russian thistle & kochia). Photo taken facing east.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400633