

Interim and Stormwater Inspection

November 8, 2023

Operator: Crestone Peak Resources Operating- #10633

Location ID: 436514

Inspection Document #: 709400634

Arapahoe County, CO

SENE Section 2 T5S R65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: State Massive 1H
Location ID: 436514

Nov 8, 2023 at 11:12:42 AM
Watkins CO 80137
United States



Photo 1. Photo taken of location sign at wellhead, facing east.

Nov 8, 2023 at 11:14:12 AM
Watkins CO 80137
United States



Photo 2. Photo taken of wells on site. Photo taken facing east.

Inspection Photos
Location Name: State Massive 1H
Location ID: 436514

Nov 8, 2023 at 11:14:04 AM
Watkins CO 80137
United States



Photo 3. Photo taken of tank battery on pad. Photo taken facing southeast.

Nov 8, 2023 at 11:15:14 AM
Watkins CO 80137
United States



Photo 4. Photo taken of interim reclaimed area of perennial grasses. Photo taken facing east.

Inspection Photos
Location Name: State Massive 1H
Location ID: 436514

Nov 8, 2023 at 11:15:35 AM
Watkins CO 80137
United States



Photo 5. Photo taken of interim reclaimed area of perennial grasses. Photo taken facing northeast.

Nov 8, 2023 at 11:15:46 AM
Watkins CO 80137
United States



Photo 6. Photo taken of interim reclaimed area of perennial grasses and stormwater sediment basin. Photo taken facing northwest.

Inspection Photos
Location Name: State Massive 1H
Location ID: 436514

Nov 8, 2023 at 11:15:53 AM
Watkins CO 80137
United States



Photo 7. Photo taken of interim reclaimed area of perennial grasses, stormwater sediment basin and weeds (russian thistle & Mullen). Photo taken facing northwest. Blue arrows indicate weeds.

Nov 8, 2023 at 11:16:26 AM
Watkins CO 80137
United States



Photo 8. Photo taken of perennial grasses in interim reclaimed area . Photo taken facing southeast.

Inspection Photos
Location Name: State Massive 1H
Location ID: 436514

Nov 8, 2023 at 11:17:11 AM
Watkins CO 80137
United States



Nov 8, 2023 at 11:17:58 AM
Watkins CO 80137
United States



Photo 9. Photo taken of topsoil stockpile. Photo taken facing north.

Photo . Photo taken of topsoil stockpile perennial grasses and weeds (russian thistle) . Photo taken facing south.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400634