

# Interim and Stormwater Inspection

October 25, 2023

Operator: Crestone Peak Resources Operating- #10633

Location ID: 472938

Inspection Document #: 709400639

Arapahoe County, CO

NWNW Section 21 T4S R65W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Grande 4-65 20-19 1AH  
Location ID: 472938



Photo 1. Photo taken of location sign at wellhead, facing east.



Photo 2. Photo taken of wells on site. Photo taken facing south.

## Inspection Photos

Location Name: Grande 4-65 20-19 1AH

Location ID: 472938

Oct 25, 2023 at 3:12:47 PM  
Aurora CO 80137  
United States



**Photo 3.** Photo taken of tank battery on pad. Photo taken facing east.

Oct 25, 2023 at 3:16:08 PM  
Aurora CO 80137  
United States



**Photo 4.** Photo taken of mowed vegetation in interim reclaimed area and drainage ditch leading to sediment basin.. Photo taken facing northwest.

## Inspection Photos

Location Name: Grande 4-65 20-19 1AH

Location ID: 472938

Oct 25, 2023 at 3:16:17 PM  
Aurora CO 80137  
United States



**Photo 5.** Photo taken of large stormwater sediment basin. Photo taken facing northeast.

Oct 25, 2023 at 3:16:57 PM  
Aurora CO 80137  
United States



**Photo 6.** Photo taken of mowed interim reclamation area of perennial grasses, outer stormwater drainage ditch. Photo taken facing south.

## Inspection Photos

Location Name: Grande 4-65 20-19 1AH

Location ID: 472938

Oct 25, 2023 at 3:17:17 PM  
1706 S Powhatan Rd  
Aurora CO 80018  
United States



**Photo 7.** Photo taken of rock rundown on large sediment basin. Photo taken facing east.

Oct 25, 2023 at 3:17:21 PM  
1706 S Powhatan Rd  
Aurora CO 80018  
United States



**Photo 8.** Photo taken of Longspine sandbur an undesirable plant species found throughout the reclaimed area. Photo taken facing south.

## Inspection Photos

Location Name: Grande 4-65 20-19 1AH

Location ID: 472938



**Photo 9.** Photo of Longspine sandbur burs in pant cuff, demonstrating mowing is not sufficient to prevent spread of seeds.



**Photo 10.** Photo taken of wheat planted in interim reclaimed area as a nurse crop.. Photo taken facing east.