

Inspection Photos
Location ID/Name: 437520, MILLER TANK BATTERY 3N-24HZ
East Battery



Photo 1
Battery



Photo 2
GMR and Pig Station



Photo 3
Vertical Separator



Photo 4
HHS



Photo 5
ECD



Photo 6
LACT



Photo 7
Pig Station



Photo 8
Horizontal Separator