

Final Reclamation Inspection

November 30th, 2023

Operator: Simcoe LLC - 10749

Location ID: 334192

Inspection Document #: 714000172

La Plata County, CO

Township: SWSW 10 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lindner Slatin A2, A4
Location ID: 334192



Photo 1. View of the project area taken from the entrance facing center.

Inspection Photos
Location Name :Lindner Slatin A2, A4
Location ID: 334192



11/30/23
+37.201198,-107.817835
187° S

Photo 2. Musk thistle observed in the western edge of the disturbance. Note: interim vegetation was not fully assessed due to snowy conditions.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515

Inspection Photos
Location Name: Lindner Slatin A2, A4
Location ID: 334192



Photo 3. Musk thistle observed along the access road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515

Inspection Photos
Location Name : Lindner Slatin A2, A4
Location ID: 334192



Photo 4. Pile of gravel observed on location. This is considered debris and needs to be removed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515