

Final Reclamation Inspection

November 30th, 2023

Operator: Enduring Resources LLC - 10663

Location ID: 306756

Inspection Document #: 714000174

La Plata County, CO

Township: NESE 7 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: West Animas 7U-3
Location ID: 306756



Photo 1. View of the project area taken from the entrance facing center.

Inspection Photos
Location Name: West Animas 7U-3
Location ID: 306756



11/30/23
+37.201794,-107.862324
91° E

Photo 2. Interim vegetation was not fully assessed due to snowy conditions. No compliance issues were observed at the time of inspection.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515