

# Final Reclamation Inspection

November 30th, 2023

Operator: Enduring Resources LLC - 10663

Location ID: 326358

Inspection Document #: 714000175

La Plata County, CO

Township: SENW 7 34N 9W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: West Animas Wheeler 7U-2  
Location ID: 326358



11/30/23  
+37.207658,-107.868342  
339° N



11/30/23  
+37.207734,-107.868419  
285° N

Photo 1. View of the project area taken from the entrance facing center.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-07914



Inspection Photos  
Location Name: West Animas Wheeler 7U-2  
Location ID: 326358



**Photo 2.** Interim vegetation was not fully assessed due to snowy conditions. No compliance issues were observed at the time of inspection.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #:067-05515