

# Final Reclamation Inspection

November 30th, 2023

Operator: Enduring Resources LLC - 10663

Location ID: 334540

Inspection Document #: 714000176

La Plata County, CO

Township: NWSE 8 34N 9W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**


**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Koshak A-3, Koshak GU A 1U  
Location ID: 334540



11/30/23  
+37.203056,-107.848501  
126° SE



**Photo 1.** View of the project area taken from the entrance facing center.  
Note: two wells share the disturbance/location.

# Inspection Photos

Location Name: Koshak A-3, Koshak GU A 1U

Location ID: 334540



11/30/23  
+37.202768,-107.848515  
117° SE



11/30/23  
+37.203237,-107.848429  
310° NW

**Photo 2.** An undesirable plant species Kochia, was observed in the active disturbance. This is considered debris and needs to be removed.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

API #:067-05515

Inspection Photos  
Location Name: Koshak A-3, Koshak GU A 1U  
Location ID: 334540



**Photo 3.** Interim vegetation was not fully assessed due to snowy conditions.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #:067-05515