

# Final Reclamation Inspection

November 30th, 2023

Operator: Enduring Resources LLC - 10663

Location ID: 306776

Inspection Document #: 714000177

La Plata County, CO

Township: SENW 8 34N 9W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Koshak B-4A  
Location ID: 306776



**Photo 1.** View of the project area taken from the entrance facing center.



API #: 067-08736





Inspection Photos  
Location Name: Koshak B-4A  
Location ID: 306776



**Photo 2.** View of oily substance in plastic container and spilling over onto concrete pad.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #:067-05515



Inspection Photos  
Location Name: Koshak B-4A  
Location ID: 306776



**Photo 3.** Interim vegetation was not fully assessed due to snowy conditions.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #:067-05515