

# Final Reclamation Inspection

November 30th, 2023

Operator: Enduring Resources LLC - 10663

Location ID: 334548

Inspection Document #: 714000178

La Plata County, CO

Township: SESW 9 34N 9W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: West Animas University 9-3, 9-1  
Location ID: 334548



**Photo 1.** View of the project area taken from the entrance facing center.



API #: 067-07840, 08741



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



# Inspection Photos

Location Name: West Animas University 9-3, 9-1

Location ID: 334548



**Photo 2.** View of erosion observed on the northern edge of the disturbance.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

API #:067-05515



# Inspection Photos

Location Name: West Animas University 9-3, 9-1

Location ID: 334548



**Photo 3.** View of scotch thistle observed in the northern interim reclamation area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #:067-05515