

## Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 314-14 Pad

Location ID: 335159



Dec 1, 2023 at 10:57:09 AM  
CO

Photo # 8160 From entrance to location



Dec 1, 2023 at 10:57:59 AM  
CO

Photo # 8161 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 314-14 Pad

Location ID: 335159



Photo # 8162 Location



Photo # 8163 Location





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 314-14 Pad

Location ID: 335159



Dec 1, 2023 at 11:00:55 AM  
CO

Photo # 8164 Location



Dec 1, 2023 at 11:01:57 AM  
CO

Photo # 8165 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 314-14 Pad

Location ID: 335159



Photo # 8166 Unused equipment



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources