

Final Reclamation and Stormwater Inspection

Date: 11/22/2023

Operator: Longs Peak Resources LLC. - 10611

Location ID: 453246

Inspection Document #: 713900129

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Jaco West 1807-1NH
Location ID: 453246



Photo 1. The photo was taken at the well location facing North. The photo illustrates the abandoned location.

Photo 2. The photo was taken at the well location facing East. Refer to the comment for photo 1.

Inspection Photos

Location Name: Jaco West 1807-1NH

Location ID: 453246



Photo 3. The photo was taken at the well location facing South. Refer to the comment for photo 1.

Photo 4. The photo was taken at the well location facing West. Refer to the comment for photo 1.