

Inspection Photos
Location Name: NIES_6-1
Location ID: 320327



Photo #1 Location sign.



Photo #2 Crude tank.

Inspection Photos
Location Name: NIES_6-1
Location ID: 320327



Photo #3 Open top P/W tank (¾ of the way full).



Photo #4 Separator.

Inspection Photos
Location Name: NIES_6-1
Location ID: 320327



Photo #5 Pump jack.




Photo #6 Pump jack behind Crude tank in distance.

Inspection Photos
Location Name: NIES_6-1
Location ID: 320327




Photo #7 Distance from pump jack to production location (977.25 feet).