

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SENW

Location ID: 311586

Date: 11/30/2023



Wellheads – Photo #07787



Separators – Photo #07788

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SENW

Location ID: 311586

Date: 11/30/2023



Nov 30, 2023 at 10:25:22
Parachute CO 81635
United States

Tank Battery – Photo #07789



Nov 30, 2023 at 10:26:33
Parachute CO 81635
United States

Insufficient Erosion Control – Photo #07792

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SENW

Location ID: 311586

Date: 11/30/2023



Insufficient Erosion Control – Photo #07791