

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 341-15 Pad

Location # 335572



Photo # 8196 From entrance to location



Photo # 8197 From entrance to location

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 341-15 Pad

Location # 335572



Photo # 8198 Location



Photo # 8199 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 341-15 Pad

Location # 335572



Photo # 8200 Location



Photo # 8201 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 341-15 Pad

Location # 335572



Photo # 8202 Location



Photo # 8203 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 341-15 Pad

Location # 335572



Photo # 8204 Location



Photo # 8205 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 341-15 Pad

Location # 335572



Photo # 8206 Thief hatch/unknown buried tank in tank battery containment/tank not labeled

Photo # 8207 Thief hatch/unknown buried tank in tank battery containment/tank not labeled