

Inspection Photos

Location Name: TEP Rocky Mountain LLC MACKLEY 127-3 Pad

Location # 324083



Photo # 8224 From entrance to location




Photo # 8225 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC MACKLEY 127-3 Pad

Location # 324083



Photo # 8226 Location



Photo # 8227 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC MACKLEY 127-3 Pad

Location # 324083



Photo # 8228 Location



Photo # 8229 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC MACKLEY 127-3 Pad

Location # 324083



Photo # 8230 Open ended load line



Photo # 8231 Open ended load line

Inspection Photos

Location Name: TEP Rocky Mountain LLC MACKLEY 127-3 Pad

Location # 324083



Photo # 8232 Unused equipment