

Inspection Photos

Location: 435722

Operator: ANADARKOE&PONSHORELLC

InspectionDate:11/29/2023

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Center of the location facing north. A uniform perennial vegetation has reestablished.



Inspection Photos



Photo 2. Center of the location facing west. A uniform perennial vegetation has reestablished.



Inspection Photos



Photo 3. Center of the location facing south. A uniform perennial vegetation has reestablished.



Inspection Photos



Photo 4. Center of the location facing east. A uniform perennial vegetation has reestablished.



Inspection Photos



Photo 5. North side of the location facing south.



Inspection Photos



Photo 6. Facing southwest toward the beginning of the transect conducted at the location.



Photo 7. Facing northeast toward the end of the transect conducted at the location.



Inspection Photos



Photo 8. Facing northwest toward the beginning of the transect conducted at the reference area.



Photo 9. Facing southeast toward the end of the transect conducted at the reference area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:435722 | Date: 11/29/2023

Cover Data Date: 11/29/2003 Inspected By: Ryan Cost
Location/Operator: 434785 Anadarko

Inspected By: Ryan Cost

434 785

Aradarko

[illegible]

2nd= second hit; P= plant species present but not hit



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Loc:435722 | Date: 11/29/2023