

# Final Reclamation and Stormwater Inspection

Date: 11/17/2023

Operator: Noble Energy Inc. - 100322

Location ID: 328891

Inspection Document #: 713900116

Weld County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: 328891  
Location ID: Tania Blue D 2-14



**Photo 1.** The photo was taken from the well location facing North. The photo illustrates the well location is dominated by russian thistle.

**Photo 2.** The photo was taken from the well location facing East. Refer to the comment for photo 1.

Inspection Photos  
Location Name: 328891  
Location ID: Tania Blue D 2-14



**Photo 3.** The photo was taken from the well location facing South. Refer to the comment for photo 1.

**Photo 4.** The photo was taken from the well location facing West. Refer to the comment for photo 1.

Inspection Photos  
Location Name: 328891  
Location ID: Tania Blue D 2-14



**Photo 5.** The photo was taken from the well location facing West. The photo illustrates the access road and flowline are dominated by russian thistle.



**Photo 6.** The photo was taken from the access road facing West. The photo illustrates the access road and flowline have large bare patches of soil.

Inspection Photos  
Location Name: 328891  
Location ID: Tania Blue D 2-14



**Photo 7.** The photo was taken from the tank battery location facing East. The photo illustrates the location has been graded.

**Photo 8.** The photo was taken from the tank battery location facing West. Refer to the comment for photo 7.