

Inspection Photos
Location Name: Pronghorn P-T-22HNB
Location ID: 432611



Photo 1 – Pumping Unit



Photo 2 – Wellhead

Inspection Photos
Location Name: Pronghorn P-T-22HNB
Location ID: 432611



Photo 3 – Riser not OOSLAT



Photo 4 – Gas Meter

Inspection Photos
Location Name: Pronghorn P-T-22HNB
Location ID: 432611



Photo 5 – Separators and ECDs



Photo 6 – Tank Battery

Inspection Photos
Location Name: Pronghorn P-T-22HNB
Location ID: 432611



Energy and Carbon Management Commission
40.39259, -104.18932, 4591.4ft
11/30/2023 13:06:01

Photo 7 – East Tanks



Energy and Carbon Management Commission
40.39266, -104.18939, 4598.1ft
11/30/2023 13:05:39

Photo 8 – Tank Battery Sign



Inspection Photos
Location Name: Pronghorn P-T-22HNB
Location ID: 432611



Photo 9 – Sign at Separator



Photo 10 – North Tank – Capacity Label



Inspection Photos
Location Name: Pronghorn P-T-22HNB
Location ID: 432611



Photo 11 – Center Tank – NFPA, Content and Capacity Labels

Photo 12 – South Tank – Capacity and Content Labels