

# Final Reclamation and Stormwater Inspection

Date: 11/15/2023

Operator: Noble Energy Inc - 100322

Location ID: 317834

Inspection Document #: 713900110

Weld County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Kern 1  
Location ID: 317834



**Photo 1.** The photo was taken at the entrance to the pad facing back along the access road East. The photo illustrates the access road remains going East.

**Photo 2.** The photo was taken at the well location facing South. The photo illustrates gas line equipment still on location.



Inspection Photos  
Location Name: Kern 1  
Location ID: 317834



**Photo 3.** The photo was taken at the well location facing West. The photo illustrates the access road remains on the right side of the photo going West.

**Photo 4.** The photo was taken at the well location facing North. The photo illustrates vegetation growing up to the gravel pad left for the tank battery equipment.





**Photo 5.** The photo was taken at the well location facing East. The photo illustrates the fence remaining at the tank battery pad and the reclamation of the well dominated by sand sagebrush, crested wheatgrass, sideoats grama and sand dropseed.

**Photo 6.** The photo was taken at the well location facing South. Refer to the comment for photo 5.



Inspection Photos  
Location Name: Kern 1  
Location ID: 317834



**Photo 7.** The photo was taken at the well location facing West. Refer to the comment for photo 5.

**Photo 8.** The photo was taken at the tank battery location facing West. The photo illustrates the gravel pad edge where the tank batteries were.