

Final Reclamation and Stormwater Inspection

Date: 11/28/23

Operator: Noble Energy Inc. - 100322

Location ID: 329077

Inspection Document #: 713900140

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: HSR-O'neil 16-29
Location ID: 329077



Photo 1. The photo was taken at the entrance to the location facing North. The photo illustrates the annual weed dominance on the location.

Photo 2. The photo was taken inside the entrance to the location facing West. The photo illustrates the former location of the tank battery is dominated by tumbleweeds and bare soil.

Inspection Photos
Location Name: HSR-O'neil 16-29
Location ID: 329077



Photo 3. The photo was taken at the well location facing North. The photo illustrates the location is dominated by tumbleweeds and bare soil.

Photo 4. The photo was taken at the well location facing East. Refer to the comment for photo 3.

Inspection Photos
Location Name: HSR-O'neil 16-29
Location ID: 329077



Photo 5. The photo was taken at the well location facing South. Refer to the comment for photo 3.

Photo 6. The photo was taken at the well location facing West. Refer to the comment for photo 3.

Inspection Photos
Location Name: HSR-O'neil 16-29
Location ID: 329077



Photo 7. The photo was taken at the well location facing Northeast. The photo illustrates a large prairie dog colony on the location.



Photo 8. The reference photo was taken near the well location facing Southwest. The photo illustrates the area is dominated by smooth brome and sunflower.