

Final Reclamation and Stormwater Inspection

Date: 11/17/23

Operator: Noble Energy Inc. - 100322

Location ID: 328396

Inspection Document #: 713900141

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Duncan D 11-13
Location ID: 328396



Photo 1. The photo was taken at the well location facing Northeast. The photo illustrates the well location is dominated by cheatgrass and russian thistle.

Photo 2. The photo was taken at the well location facing Southwest. Refer to the comment for photo 1.

Inspection Photos
Location Name: Duncan D 11-13
Location ID: 328396



Photo 3. The photo was taken at the well location facing North. The photo illustrates russian thistle and cheatgrass dominate to the edge of the disturbance where blue grama is more dominant.