

Interim Reclamation and Stormwater Inspection

Date: 11/28/23

Operator: Kerr McGee Oil & Gas Onshore LP - 47120

Location ID: 435425

Inspection Document #: 713900152

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: NRC 3C-4HZ
Location ID: 435425



Photo 1. The photo was taken at the tank battery location facing West. The photo illustrates the operator well signs.

Photo 2. The photo was taken at the tank battery location facing North. The photo illustrates the tumbleweeds (kochia) growing around the boundary of the pad and well location.

Inspection Photos
Location Name: NRC 3C-4HZ
Location ID: 435425



Photo 3. The photo was taken at the tank battery location facing Northwest. The photo illustrates rill erosion carrying sediment offsite.



Photo 4. The photo was taken North of the tank battery location facing Southeast. The photo illustrates the erosion issue in photo 3 from the other side.

Inspection Photos
Location Name: NRC 3C-4HZ
Location ID: 435425




Photo 5. The photo was taken at the well location facing West. The photo illustrates the tumbleweeds growing along the edge of the pad.