

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PARACHUTE RANCH-67S96W/26SWSE

Location ID: 334405

Date: 12/4/2023



Location Entrance – Photo #07813



SE Corner of Location – Photo #07822

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PARACHUTE RANCH-67S96W/26SWSE

Location ID: 334405

Date: 12/4/2023



Wellheads – Photo #07814



Separators – Photo #07818

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PARACHUTE RANCH-67S96W/26SWSE

Location ID: 334405

Date: 12/4/2023



Tank Battery – Photo #07821



Storage of Supplies/Equipment – Photo #07819



Inspection Photos

Location Name: CAERUS PICEANCE LLC, PARACHUTE RANCH-67S96W/26SWSE

Location ID: 334405

Date: 12/4/2023



Insufficient Materials Handling/Spill Prevention – Photo #07815



Insufficient Materials Handling/Spill Prevention – Photo #07817